

Industry: Automotive

Project Description: Design and supply wireless traffic panel and configure wireless hardware

1. Please answer the following questions using the scale provided:

	Strongly Agree	Agree	Slightly Agree	Slightly Disagree	Disagree	Strongly Disagree
Knowledge/Expertise – industry, application & technical	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Service – responsive, quick, professional	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Communication – proactive, complete, timely	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Pricing – competitiveness, value for the dollar	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trustworthiness – commitment, will deliver, overall relationship	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2. Please identify two areas in which we excelled:

Responsiveness and communication.

3. Please identify two areas in which we could improve:

A hiccup with one port that was missed, brought back to be repaired. JMP responded well.

4. Please share any other comment you might have about this project or JMP in general.

5. How likely is it that you would recommend JMP to a friend or colleague? (1 = not at all likely, 10 = extremely likely)

1 2 3 4 5 6 7 8 9 10

Why did you give us this score?

_____ was really easy to work with and definitely has great skills in understanding what the customer wants. There were a couple hiccups with the final product. We had to send it back because a part was missing from the original panel. Also, I think a little more time could have been spent on the actual design of the box. There was a flaw that could have been pretty easily avoided.

JMP Comments: Thank you for the feedback. We have reviewed our internal processes with the team that should prevent this from happening in the future.

